

# Boats, Bridges and Back-ups

Roger Stokes BSc CEng FIChemE MIE

EPSC European Conference on Plant & Process Safety  
December 2024



# Contents

- Boats and Bridges
- Why do we need a back-up?
- Some causes of power / energy supply failure
- Consequences of power / energy failure
- Understanding the hazards and risks
- Types of back-up systems
- Human Factors
- Design and testing of back-ups
- Process Industry examples where back-ups didn't work
- Conclusions

# BOATS AND BRIDGES





# MV Dali/ Francis Scott Key Bridge, Baltimore

## 26 Mar 2024 at 0129 hrs

- 6 Fatalities / 1 major injury (roadworkers)
- 1 injury on board

### Sources of data

- NTSP Preliminary Report - 14 May 2024
- Investigation update - 24 June 2024
- Dali Shipboard Machinery Examination and Record of Electrical Testing on April 1–29, 2024 – 11 Sep 2024
- US Claim against MV Dali owners - 18 Sep 2024
- WGOW Shipping (Sal Mercogliano, YouTube)

Changes expected as investigation continues




[ntsb.gov/investigations/Documents/DCA24MM031\\_PreliminaryReport%203.pdf](https://www.ntsb.gov/investigations/Documents/DCA24MM031_PreliminaryReport%203.pdf)



# MV Dali


- Registered: Singapore
- Length: 289 metres ~ 100,000 tonnes (gross)
- Engine: single 41,480 kW low-speed two-stroke diesel engine
- No gearbox/ clutch
- Compressed air to start/ reverse
- Propeller 27 rpm – 80 rpm
- Single rudder
- Fuel: Light oil (Low sulphur) and heavy fuel (outside emissions control areas)



NTSB Preliminary Report

# Electrical Systems

- HV power (6.6kV) to HV bus by up to four diesel generators
- Two operating (DG3 and DG4) at the time of the incident.
- DG2 “on automatic standby”
- Transformer TR2 isolated
- Transformer TR1 on line
- Emergency generator on LV bus



NTSB  
[ntsb.gov/investigations/Documents/DCA24MM031\\_PreliminaryReport%203.pdf](https://www.ntsb.gov/investigations/Documents/DCA24MM031_PreliminaryReport%203.pdf)

# Critical Systems

Some key electrical systems

## HV system

- Engine lube oil pumps
- Bow thruster (B/T)
- Refrigerated containers


## LV system

- Lighting
- Steering Gear pumps (x3)
- Engine cooling water pumps

- Fuel Pumps – engine, generators




# MV Dali, Baltimore Bridge collapse, 26 Mar 2024



# Events (Preliminary Report, subject to change)

- 01:24:58 hrs SOG ~ 9 knots<sup>1</sup>
  - HR1 and LR1 tripped – LV systems lost power
  - Most bridge systems lost power
  - Engine shuts down (fuel/ lube/ cooling)
  - Steering pumps (x3) lost power
- 01:25:57 power restored (“Manual reset HR1, LR1”<sup>2</sup>)
- EG started – timing tbc (“over 1 minute”)
- DG2 started – timing tbc
- 01:26:13 pilot orders 20° port rudder
- 01:27:01 pilot ordered anchor drop
- 01:27:03 second power failure HV and LV bus
  - DGR3 and DGR4 opened due to fuel starvation to generator
- 01:27:23 pilot ordered 35° port rudder
- 01:27:36 power restored
- 01:29:10 Dali strikes pier 15 of Francis Scott Bridge



<sup>1</sup> Video times showing power failure adjusted to match NTSB report

<sup>2</sup> US Claim against MV Dali owners

# Consequences of power loss – cascade failure

- Engine stop - not self-sustaining for fuel, lube or cooling
  - Common cause failure
  - Not quick to restart / put astern
- Loss of hydraulic oil to rudder – slow movement
- Loss of effectiveness of rudder - less flow over it
- Loss of HV to bow thruster - not very effective at speed anyway
- Anchor drop attempt – required local attendance as bridge approaching, so dropped but not locked off




# Pier Fender

- 100 ft x 84 ft crushable concrete box and timber fender system
- Clearly not sufficiently large/robust



# Cause – Power outages

- First undervoltage release blackout: Loose connections on HR1's termination block
  - Possibly vibration
- Auto-switchover to No.2 transformer not operating “disabled”
- Second blackout : No 3 and 4 generators for US ECA areas – burn marine gas oil
  - Set up “temporary” fuel pump for 3 & 4, to use low sulphur fuel - that could not recover automatically after first black-out. (MOC)
  - Fueled only by a small emergency air-driven pump, the generators were starved of fuel and slowed down until switchgear tripped out.



Vibration reduction measures !


# Drone footage (NTSB)





# MV Dali – The Barriers that failed

- Tugboat
  - Not available at critical point of departure (procedure?)
- Power loss due to electrical / vibration problems
  - No available back-up to allow main engine to run (design / maintenance?)
- Transformer not set to auto-changeover
  - Or set up on shared 50:50 load (procedure?)
- Fuel pump for generators
  - Not lined up for restart from power loss (MOC ?)
- Emergency Generator (LV) not started up quickly enough
  - Greater than 45 seconds (design/ testing / procedure ?)
- Pier Fendering system
  - Not effective for speed/ tonnage (creeping change?)
- Plus plus ...



# Current Status

- MV Dali arrived Norfolk, Virginia June 25<sup>th</sup> 2024
- Containers were offloaded by August 20<sup>th</sup> 2024
- MV Dali sets sail (empty) for repairs in China Sep 20<sup>th</sup> 2024
  - Avoiding canals (Panama/ Suez) – Costs?
  - Via S Africa / Malacca Straits to Shanghai
- Nov 4 – South China Sea
- Nov 13 – arrived at Fujian Huadong Shipyard, China

# MV Dali – En route to China






# MV Dali arrival China – Nov 13<sup>th</sup>, 2024



# BACKUPS



# Why we need back-ups

- Industrial processes at risk due to a sudden loss of energy supply (mainly, but not wholly electrical power)
  - Physical damage/ injury and/or environmental incidents
- Require a continuous supply of energy for the safe operation of “Essential Services” including:
  - Process control computer
  - Plant, machinery and instrumentation
  - Services including
    - Steam
    - Air
    - Water (process water and cooling water)
    - Nitrogen
    - Lubrication
    - Hydraulics
  - Emergency systems
    - Vent scrubbers, fire systems

# Essential Services

- Unlikely to be able to sustain operations
- Services that are crucial for safe shutdown
- Identify through HAZOP / LOPA (but not always)
- Identify common cause failures – e.g. “what-if” or FMEA study
- Consider potential for cascade failure



# Some causes of power supply failure

- Fires in substations and switch-houses
- Switchgear faults/ human error when working on switchgear
- Underground cable faults
- Excavations and other works damaging underground cables / gas piping
- Cranes/ tipper trucks contacting overhead cables
- Lightning strikes
- Failures in external grid network
- Storm/ flood / tsunami

# Some Consequences of Power Failure

Equipment damage and loss of containment/ injury due to:

- Loss of process control
  - Uncontrolled chemical reaction / nuclear reaction
  - Loss of cooling
  - Blockage due to stoppage of solids/ slurry/ plastics
- Rapid cooling of fired equipment
  - Glass Furnaces
  - Fired heaters/ reformers
- Potential for cascade failure
  - Power Loss – Control systems – Air systems – Nitrogen systems – Cooling Water – Communication Systems
- Damage during restart
  - Due to unplanned shutdown



# Understanding hazards and risks

- Usually at the design stage via HAZID/ HAZOP / LOPA
- Identification of critical services, including:

- Safety Critical instrumentation and electrical drives
- Instrument air compressors
- Emergency scrubbers (vent fans and circulation pumps)
- Steam boilers (feed water pumps and exhaust fans)
- Cooling water pumps

- Refrigeration systems
- DCS control systems
- Emergency lighting
- Firewater pumps
- Seal water pumps
- Reactor agitators
- Nitrogen
- Hydraulic systems

# Types of back-up systems

## Examples:



- Secondary independent power supply
- UPS
  - Battery, uninterrupted but limited capacity
- Diesel powered standby equipment (pumps, compressors, generators)
  - Longer operating period than UPS
  - Start-up time, synchronisation time
  - Compressed air start for higher reliability, e.g. nuclear
- Compressed air storage
- Nitrogen bottles
- Hydraulic packs
- And many more ...



# Human Factors

- Procedures may be limited to failure of individual services
  - Not a cascade failure of services
- Operators have little or no experience of power failure
  - Until it happens
- Operator overload
  - Decision making
  - Resources – e.g. requirement to open/ close valves manually
  - Assumptions about status of equipment (blank DCS screen)

- Design and testing of Back-ups



# Design Considerations

- Standards are available
  - NFPA 110 , 111, IEEE 446, IAEA SSR-21
- Holistic approach when considering power/ energy failure
  - Include electrical and process specialists, process safety engineers, technicians, and emergency response planners
- Design to allow complete end-end testing
  - Without risking loss of power to process

# A testing problem

- If the test fails, there is a risk of tripping the facility
  - To be safe, leave it until the next shutdown
- Perception that the back-up is reliable enough
  - Fingers crossed – The “Titanic approach”
- Testing up to a point...
  - Not synchronized
  - Not run for more than xx minutes
  - Not load tested
  - Faults recorded and fixed, but causes not resolved




# AN EXAMPLE FROM THE PROCESS INDUSTRY



# Loss of Power – Major Petrochemical Complex

- Dual, independent power supplies on separate poles
- 14 diesel back-up generators at various locations
  - To allow safe shutdown of facilities
- 56 UPS (battery backups)
- Steam supply includes “high integrity boiler”
  - Steam turbine-driven feed pumps/ combustion air fans
- Steam turbine-driven air compressors
  - With back-up from nitrogen system for instrument air
- Both Power supplies failed
- Only 3 effectively supplied power
- 5 UPSs failed to work
- Boilers tripped
- Air compressors tripped

# Key events – cascade failure of power/air/ water



# Consequences

- Failure of furnace tubing
  - Thermal stress and overtemperature
- Backflow of hydrocarbons due to downstream pressure control valve failing closed
  - Backpressure on furnaces
  - Operators could not close manual valves in time
- Uncontained fires in multiple furnaces
- £MM repair costs/ environmental damage





# Key Learning

- External power supplies were not independent - subject to common cause failure.
- Inadequate design, maintenance and testing of emergency generators
  - Not synchronized – routine test was to mechanically start the generators and verify voltage is generated.
  - No simulated load testing of generators was conducted, and the tests did not include electrical synchronisation.
- Failure mode of the control valve on backup to instrument air supply was incorrect.
- Failure to consider total loss of services in the design/emergency planning/human factors, including inability to manually close outlet valves from each furnace in time.

# Conclusions





# Conclusions


- Multiple, reliable energy sources are required for safe operations
- Failure of one or more of these energy sources can lead to major incidents.
- Consequences are mitigated by the provision of back-up supplies for critical services.
- Design and testing of backups must be carefully considered to ensure they are sufficiently reliable.
- Emergency procedures should also consider the potential failure of the back-up supplies and include procedures, training, and exercises to minimise the hazardous consequences of such events.
- It is healthy to maintain a “sense of chronic unease” when it comes to emergency back-up systems.

# CONTACT US

## ROGER STOKES

 BakerRisk Europe Limited, Regus House,  
Heronsway, Chester, CH4 9QR

 +44 (0)1244 792040

 [rstokes@bakerrisk.com](mailto:rstokes@bakerrisk.com)



# WE HAVE ANSWERS

## SERVICES

Better Risk Management Starts Here



Accident  
Investigation



Functional and  
Electrical Safety



Fire Protection and  
Insurance Risk



Consequence and  
Risk Modeling



Qualitative Hazard  
Identification and  
Risk Assessment



Protective  
Structures



Testing



Low Carbon Energy

## BAKERRISK LEARNING CENTER



## LOCATIONS



San Antonio	Canada
Houston	Egypt
Chicago	United Arab Emirates
Los Angeles	United Kingdom

